

OUT54116

*Multi*  
P 211957Z  
FM NPIC WASHDC  
TO RUCSBR/SAC OFFUTT AFB OMAHA NEB  
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
RUCVAA/2D RTS BARKSDALE AFB LA  
RUEAHQ/DIA WASHDC  
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
RUEPIA/CIA WASHDC  
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
RUWGAA/2AF BARKSDALE AFB LA  
BT  
S E C R E T CITE NPIC 2948.

1964 SEP 21 21 33Z

HFS

CJS

CFC

PNS

ACL

Grace (File)

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-15 WAS USED IN MISSION 3946 FLOWN 17 SEPTEMBER.

PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER IS NOTED INTERMITTENTLY  
ALONG BOTH EDGES THROUGHOUT. MINOR EDGE STATIC IS PRESENT INTER-  
MITTENTLY THROUGHOUT. SEVERAL FINE LONGITUDINAL PLUS DENSITY  
ABRASIONS OCCUR PARALLEL TO THE EDGE. AMONG THESE, FOUR  
CONSISTANT LINES RECUR PERIODICALLY 2.45", 2.65", 5.15", 5.25"  
FROM THE INBOARD EDGE. A DIG ON FRAME 799 HAS AN ASSOCIATED  
MINUS DENSITY STREAK WHICH CONTINUES THROUGH FRAME 837 PARALLEL  
TO AND 2.4" FROM THE INBOARD EDGE. CRIMPS WERE NOTED ON FRAMES  
36 AND 190. MINOR DENSITY LEVEL CHANGES APPEAR ON FRAMES 48

AND 2180. A MINUS DENSITY DOT WITH A TAIL IS FOUND ON FRAME 122. A DIG WITH AN ASSOCIATED PLUS DENSITY STEAK APPEARS ON FRAME 486. MANUFACTURER'S SPLICES ARE LOCATED IN FRAME 731 AND 1346 WITH ASSOCIATED STATIC NOTED ON FRAMES 732 AND 1348.

C. 9L SIDE: SMALL EDGE STATIC DISCHARGES ARE PRESENT ON BOTH EDGES THROUGHOUT THE MATERIAL. ROLLER-INDUCED DISCHARGES ALSO APPEAR ALONG BOTH EDGES IN FRAMES 000-599 BUT GRADUALLY DISSIPATE THEREAFTER. MINOR PROCESSING STREAKS ARE EVIDENT INTERMITTENTLY. FRAMES 224-229 CONTAIN AN IRREGULAR PLUS DENSITY STREAK. SCRATCHES AND OR ABRASIONS DEGRADE FRAMES 896, 897 AND 2196. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1557.

D. BOTH SIDES: THE FRAME COUNTER JAMMED ON NUMBER 1000 (TITLE NUMBER 1000) THEN RESUMED OPERATION IN TITLE NUMBER 1605. THE MALFUNCTION RECURRED IN TITLE NUMBER 1931 AND DID NOT CLEAR FOR THE REMAINDER OF THE MISSION. IN ADDITION, THE COUNTER NUMBER 1300 WAS REPEATED DURING THE OPERATIONAL SEQUENCE. BOTH SIDES CONTAIN TITLED FRAMES 0000-2196.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. DUPLICATE POSITIVE:

A. THE PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE OR DEGRADE 30 PERCENT OF THE PHOTOGRAPHY.

S E C R E T

-END OF MESSAGE-